

Message in instrument cluster "Add 1l of oil at next filling station"

Topic number	LI18.40-P-070746
Version	1
Function group	18.40 Oil level/oil pressure sensor
Date	01-08-2020
Validity	Model 205 facelift with M177
Reason for change	Cause and remedy revised
Reason for block	

Complaint:

Message in instrument cluster "Add 1l of oil at next filling station"

Cause:

PTCU software

Remedy:

Do not replace any parts, a permanent remedy is being prepared.

Immediate Measure:

- Drain and collect oil
- Add 7.8-8 l of oil

Note:

This oil level corresponds to the minimum mark

Symptoms
Power generation / Engine lubrication/oil cooling / Indicator lamp / Engine oil level indicator lamp / lit
Power generation / Engine lubrication/oil cooling / Display message / Oil sensor message

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			18336 **	