

Audible fan noise from area of center console

Topic number	LI82.85-P-070744
Version	1
Function group	82.85 Navigation and Communication systems
Date	01-14-2020
Validity	Model series 253 with code 547/548/549 Model series 293 with code 547/548/549
Reason for change	
Reason for block	

Complaint:

During an extended drive cycle audible fan noise may be heard coming from the area of the center console.

Cause:

The MBUX multimedia system (A26/17) fan may switch to maximum speed in response to increased cooling demand on the control unit.

Remedy:

The system is working as designed. Do not replace any parts.

Symptoms
Communication/information / Entertainment / Overall system/operation / Miscellaneous
Body / Air conditioning / Heater / Noise
Body / Air conditioning / Air conditioning / Noise