

Technical Journal

TITLE:

Audio switches on steering wheel, no function

REF NO: TJ 32033.5.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2020-01-08	STATUS DATE: 2020-01-14	
FUNC GROUP: 6414	FUNC DESC: Steering wheel, control buttons	Page	1 of 3	

"Right first time in Time"

Attachment

File Name	File Size
TJ 32033 SWSM.JPG	0.0437 MB

Vehicle Type

Type	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
225						2019-2019		-	201817-201945
227						2019-2019		-	201846-201945
234						2017-2017		-	201617-201945
235						2017-2019		-	201624-201945
236						2017-2019		-	201646-201945
238						2018-2019		-	201646-201945
246						2018-2019		-	201717-201945
256						2016-2019		-	201505-201945

CSC Customer Symptom Codes

Code	Description
EV	Audio other/Steering wheel audio controls do not work
6B	Buttons/control knobs on centre console (Media, communication and navigation)/No/reduced/incorrect function
DQ	Navigation/Steering wheel navigator controls do not work

Technical Journal 32033.5.0



VST Operation Number

VST Operation Number	Description
39432-2	Steering wheel switch module SWSM replace

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

*This TJ is rewritten in its entirety

If the audio switches on steering wheel have no or intermittent function, see advice under Service.

SWSM = Steering Wheel Switch Module

SERVICE:

Replace the steering wheel switches according to VIDA instructions.

New improved steering wheel switches were introduced week 46, 2019 and come as a complete assembly including both switches and wire harness, see attached picture <u>TJ 32033 SWSM.JPG</u> The new steering wheel switch assembly supersedes the old steering wheel switches.

New Part Number for Steering Wheel Switches:

PN **32266342** Charcoal (Variant code: RU05)

PN 32266343 Crystal Look (Variant code: RU02 or RU06 or RU08 or RU09)

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP number: 39432-2

VEHICLE REPORT:


Yes, please submit a Vehicle Report if any case of new Audio Switch failures. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 6414.

To view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 3 2020-01-14



Technical Journal 32033.5.0



2020-01-14 Page 3 of 3