



Parts Bulletin

TITLE:

**Service Action S29987: Thermostat Monitoring
Model Year 2018-2020 S60T8, V60T8, S90T8, XC60T8, XC90T8**

GROUP: 28	CAT/NO: S29987	REFERENCE BULLETINS: QB S29987	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2020-01-28	STATUS DATE: 2020-01-28
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S29987

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S29987 on certain model year 2018 - 2020 S60T8, V60T8, S90T8, XC60T8, XC90T8 vehicles.

Volvo has identified that the Engine Control Module (ECM) may not correctly monitor the coolant thermostat (between 20 to 60 degrees Celsius). This condition can result in increased vehicle emissions and non-compliance with On Board Diagnostics (OBD) II requirements.

The corrective action is a total upgrade.

Service Action S29987 affects 7,923 vehicles in the U.S and 1,066 in Canada.

The following part numbers apply:

Part Number	Description	Qty
31483292	Total Upgrade XC60T8, XC90T8	1
31493704	Total Upgrade S60T8, V60T8	1
31472405	Total Upgrade S90T8	1