

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	02	20	2020	<b>Expires on</b>	03	05	2020
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Visit: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Plpe						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
From: Technical Research & Support Group  
RE: Request for Visit: 2014-2019 MDX & TLX Fuel Leak at Fuel Joint Plpe

**This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.**

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2014-2019 MDXs & 2015-2019 TLX with a client complaint of a fuel leak at the fuel joint pipe. To better understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirement:

1. Must trace the fuel leak to the fuel joint pipe at the fuel pump or the rail connection.
2. No repair has been attempted for this issue.
3. No prior history of the fuel joint pipe replacement.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.