

SS: 1034639 TBB Minotour Entrance Door seal gap

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of gaps in the Entrance door on the hinge side.

Applicable Vehicles

2020 Minotours

Symptoms

Air Intrusion, cosmetic issue

Solution:

Adding a Rubber seal TBB 26061370 in the track and then reinstall the original door seal. This will fill the Void. Attach PDF

