

SS: 1034650 TBB Minotour water intrusion

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to report a product improvement in preventing water / dust intrusion in the drivers vestibule area.

Applicable Vehicles

Minotours




Symptoms

Noticing floor board carpet getting wet

Solution:

Add TBB 68000160 at the transition of the steel floor and cab on the flat portion completely across the cab. Tuck TBB 68000160 under the steel floor raised location. This was also added to the Dust intrusion chart TBB 215626. First unit 2010455 Date 2/25/20


BIW – MINO



Before



After



Add 68000160 at transition of steel floor to cab on flat portion completely across the cab. Tuck 68000160 under steel floor at raised locations.

Cowl Sealant – K3A20 (68000160)