ATTENTION: GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER	IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right. © 2020 Subaru of America, Inc. All rights reserved.	QUALITY DRIVEN® SERVICE
SERVICE INFORMATION BULLETIN		
APPLICABILITY:	2013MY Legacy and Outback 2014-20MY Forester 2012-20MY Impreza 2013-20MY Crosstrek 2015-20MY WRX 2016-20MY BRZ 2019MY Ascent	NUMBER: 07-169-20 DATE: 02/21/20
SUBJECT:	Push Button Start Switch- Label C	hange

INTRODUCTION:

This Service Information bulletin describes a change made to the labels applied to the push to start switches used on the models listed above. There has been NO change made to the operation or functionality of the switches. The label change was made for compliance reasons in the Indonesia, Argentina and China markets.

PART INFORMATION:

The part number switches listed below include the new labels. Any changes identified between the OLD and NEW part labels can be disregarded.

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

Service procedures for switch replacement remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.