

Disengage High Voltage System before Performing a Terminal 30 Reset

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	February 21, 2020	Original document

Technical Background

When Taycan service work requires a terminal 30 reset, disengaging the high voltage system offers additional protection to the technician and to the vehicle electrical system.

Service Information

Before performing a terminal 30 reset, use the high voltage service interrupt switch to isolate the high voltage system from the 12 V system.

Search Items

T30, KL30, klamp 30, clamp 30, full battery reset

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.