

CAMPAIGN LAUNCH STATUS

N412 RECALL–20MY EVOQUE & N430 20MY EVOQUE AND DISCOVERY SPORT - EVAPORATIVE EMISSIONS PURGE VALVE



SAFETY RECALL N412 EVOQUE HEADLINER	
AFFECTED MODELS	20MY EVOQUE
NAS VOLUME AFFECTED	3444 US of which 169 are in retailer stock
REPAIR	In temps below 25F, the adhesive bond attaching a metal plate to the headliner may reduce which can cause the plate to detach during an airbag deployment
REPAIR TIME	2 hrs
LAUNCH	February 7 th 2020
Notes	2 nd customer mailing by 2/28/2020

SERVICE ACTION N430 20MY EVOQUE & DISCOVERY SPORT - EVAPORATIVE EMISSIONS	
AFFECTED MODELS	20MY EVOQUE and DISCOVERY SPORT 2.0L
US VOLUME AFFECTED	20,658* of which 7757 are unsold
REPAIR	Revised engine control module software is required to fix a calibration concern that could potentially increase evaporative emissions
REPAIR TIME	Est 0.2 hrs
LAUNCH	February 7 th 2020
Notes	* Population under review and may be reduced