

Latest Vehicle Concern Fixes



AJ20P6 Timing Chain	2019 Onward Range Rover, RR Sport MHEV equipped with AJ20P6
<p>Customer Voice:</p> <ul style="list-style-type: none"> The engine does not start. <p>Technical Description:</p> <ul style="list-style-type: none"> Inspection finds the camshafts not turning when the engine is cranking. <p>Status:</p> <ul style="list-style-type: none"> This topic is currently under investigation. Create an EPQR as soon as this is identified and include pictures of the following items whenever possible: <ol style="list-style-type: none"> Production markings on the chain. Detailed pictures of the broken link including as many pieces as can be found. Pictures of the broken link on the transversal sides at the maximum possible magnification where the picture is still clear. 	<ol style="list-style-type: none">   

