

# Latest Vehicle Concern Fixes



Quiescent Drain After A State Inspection	18-20MY Discovery, Discovery Sport, RR Velar and F-PACE
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>The vehicle will not start.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>There is a quiescent drain causing a RSA on vehicles that just had a state inspection performed or an unsupported device has been installed into the OBD port.</li><li>This results in the CAN bus not shutting down.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>IP software is available to prevent the quiescent drain .</li><li>SSM74635 for Jaguar and SSM74634 for Land Rover has been published for vehicles equipped with a midline instrument panel.</li><li>A UPS is currently on sign-off</li></ul>	

