

Subject: Engineering Information – Vehicle Exhibits No Crank Condition During Start/Stop Event and/or When Starting Vehicle Using the Start Button On the Dash

This PI has been revised to end the need for information from the field. Please discard PIE0515A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2020	-	-	Equipped with 5.3L, 6.2L Engines (RPOs L84, L87)	-
GMC	Sierra 1500 (New Model)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released March 06, 2019 Revised October 25, 2019 – Updated the Subject, Condition, Correction, Contact and Warranty Information. Revised January 28, 2020 – Ended the need for further information from the field.