

Subject: Engineering Information – Steering Wheel Shaking While Hands are on Steering Wheel and Brakes Not Being Applied

This EI has been revised to end the need for information from the field. Please discard PIE0542.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2020	-	-	-	-

If you encounter a vehicle with the above condition, refer to Bulletin 19-NA-185 for further diagnosis.

Version	2
Modified	Released October 03, 2019 January 10, 2020 – Ended the need for further information from the field.