Subject: Engineering Information – No Crank / No Start

This PI has been revised to end the need for information from the field. Please discard PIE0549.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------------|-------------|------|------|----|--|------------------------------------|
| | | from | to | from | to | | |
| Cadillac | XT4 | 2019 | 2020 | - | - | Equipped with 2.0L Engine (RPO LSY) | - |
| Chevrolet | Silverado 1500 | | | | | Equipped with 2.7L | Equipped with 8 Speed Automatic |
| GMC | Sierra 1500 | | | | | Engine (RPO L3B) | Transmission (RPO MQE) |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| Version | 2 |
|----------|---|
| Modified | Released December 02, 2019 Revised January 27, 2020 – Ended the need for further information from the field. |