



VNR 660 - upper bunk restraint too short

Description:

8 trucks built with the incorrect upper bunk restraint which was too short.

Corrective Action:

Remove the existing upper bunk restraint and replace it with the new restraint and torque to 68NM. The new Restraints have been shipped to Paso Robles Truck Center at no charge.

UCHP SCC CODE: S7452

EXPIRATION DATE: 8/31/2020

CAUSAL PART NUMBER: 20566670

UCHP Labor Code:

1720-16-09-01 Campaign, General 1.0hr

PARTS MARKUP: na

PARTS LIST:

na

FOR MORE INFORMATION CONTACT: Robert Wise

robert.wise@volvo.com

VIN List

4V4WC9EH9LN267721
4V4WC9EH7LN267717
4V4WC9EH7LN267720
4V4WC9EH8LN267712
4V4WC9EH1LN267714
4V4WC9EH6LN267708
4V4WC9EH4LN267707
4V4WC9EH2LN267706