

Technical Journal

TITLE:

Storage box under driver seat, handle loose

REF NO: TJ 35399.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2020-01-30	STATUS DATE: 2020-02-05	
FUNC GROUP: 8529	FUNC DESC: Miscellaneous	Page	1 of 3	

"Right first time in Time"

Attachment

File Name	File Size
PictTJ35399.pdf	0.2705 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2019-9999		0000001-0999999	201746-999952

CSC Customer Symptom Codes

Code	Description
T4	Interior moldings and fasteners/Interior fasteners loose, poor fit, warped

Text

DESCRIPTION:

If the handle for the storage box under drivers seat feels loose, see Service.

SERVICE:

The spring can come loose if the driver tries to grab the handle but reaches too far and grabs under the handle. Just push the spring in place again, use a finger or screw driver or similar. It is not needed to remove the box. See "PictTJ35399.pdf". The spring is in the correct position in the picture. Inform the customer.

Technical Journal 35399.1.0



*Warranty claim info:

No warranty claim accepted for a job described in this TJ

VEHICLE REPORT:


Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8529.

To view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 3 2020-02-05



Technical Journal 35399.1.0



Pict TJ 35399

2020-02-05 Page 3 of 3