VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Panoramic sunroof, noise or hard to close

REF NO:	ISSUING DEPARTMENT:		ARKET:
TJ 35154.1.0	Technical Service		s and Canada
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:
	7510 Volvo Car USA	2020-02-04	2020-02-07
FUNC GROUP: 8360	FUNC DESC: Roof hatch	Page	1 of 7

"Right first time in Time"

Attachment

File Name	File Size	
TJI-517920-1_1_0_en-US.PDF	1.1129 MB	

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224						2019-2020	70	0000001-0041515	201835-201934

CSC Customer Symptom Codes

Code	Description	
B2	Sun/moon/convertible roof/Squeak/rattle	

VST Operation Number

VST Operation Number	Description	
98738-2	Panoramic roof adjust acc. to TJ 35154	
99922-2	General reimbursement acc. to TJ/QB	

DTC Diagnostic Trouble Codes

Text

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2020 VOLVO CAR USA, LLC

Technical Journal 35154.1.0



DESCRIPTION:

If noise occurs during closing/opening or if there is difficulty in closing the panoramic roof panel, follow instruction under "Service".

SERVICE:

Inspect the rubber lip, left and right side of the front panoramic glass panel, for deformity and if confirmed perform repair as per attached TJ instruction.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 98738-2 and 99922-2

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8360.

To view TJ attachment continue to next page. This TJ has one attachment.


Volvo	Car Customer Service	TJ Instruction VCC-517920-1		
Title	Sun roof	Page	1(5)	
Action	Adjustment	Operation number:	99922-2	
			98738-2	

Issue	Date	Reason
1	2019-11	First issue

Affected vehicles


Model year 2019, 2020	Model
2019, 2020	S60 (19-)

Color symbols





Check

Note! If noise is evident, follow information below to correct the problem.




Adjustment






Measure

TJ Instruction VCC-517920-1



Removal

Lower the headlining, refer to:
Removal, replacement and installation
8 - Body and interior
85 - Interior
855 - other upholstery




Adjust to the specified value.

Page 4 (5)

Page 5 (5)

Installation



To install, reverse the removal procedure.