



Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Golf, GTI, Golf R, Passat, Beetle, Beetle Convertible, Arteon, Tiguan LWB, Atlas	2014-2020	CHHA, CNSA, CNTA, CNSB, CPKA, CPRA, CXBA, CXBB, CXCA, CXCB, CXDA, DCGA, DDSA, DDSB, DKFA, DGUA, DLRA, DLRB	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2058888/1	3/6/2020	15-20-01	Original publication.

Technical Background

After performing work on the chain drive (chain/tensioner replacement), the adaptation value in the engine control module must be adapted.

Service

Switch ON the ignition and select the following menu items on the Vehicle Diagnostic Tester: 01 - Engine electronics > Guided Functions > Adaptation after repair work on the chain drive.

With updates to ODIS, the test plan is now located under Basic Settings > Chain Elongation Reset after Chain Replacement.

If the test plan isn't located in the referenced place within this circular send a feedback using the help button.

Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.