

Vibrations from steering after changing to winter tires

Topic number	LI46.35-P-070977
Version	1
Function group	46.35 Electrical steering
Date	02-10-2020
Validity	177.051 177.151 118.351 118.651 247.651
Reason for change	
Reason for block	

Complaint:

Vibrations when starting off with steering wheel turned slightly (after changing to winter tires)

Cause:

Steering software may need to be updated

Remedy:

New software expected to be available from March 2020. Document will be updated when software is available. This does not affect the drivability of the vehicle.

Symptoms
Chassis/suspension / Steering system / Steering wheel / Vibrates