



Service Bulletin


Bulletin No.: 20-NA-045


Date: February, 2020

INFORMATION

Subject: Black Sealant Material Visible on Wheel Edge

Brand:	Model:	Model Year:		VIN:		Engine:	Additional Options (RPOs):
		from	to	from	to		
Cadillac	CT4	2020	2020			All	Equipped with TIRE ALL-235/40R18 SL 91V BW AL3-S (RPO Q4A)

Involved Region or Country	North America, Middle East
Condition	 <p style="text-align: right; font-size: small;">5519310</p> <p>Some customers may comment on black sealant material visible on the edge of the wheel, resulting in a negative cosmetic appearance.</p>

<p>Cause</p>	 <p>5519311</p> <p>This may be caused by sealant material being transferred during the mounting process while using a clamp-type tire mouter.</p>
<p>Correction</p>	<p>If you encounter a vehicle with the above concern, clean the material off using the proper cleaning materials.</p>

Service Procedure

If you encounter a vehicle with the sealant visible, clean the wheel using the tire bead and wheel mounting lubricant, GM Part Number 12345884 (U.S.) and 88863415 (Canada).

Before Cleaning Wheel



After Cleaning Wheel



5524090

Version	1
Modified	Released February 24, 2020

