

68-17-02TT - Driver or Passenger Vanity Light Inoperative

## Condition

### **ATTENTION:**

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN. TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

| Applicable Vehicles |           |           |             |                |              |  |  |
|---------------------|-----------|-----------|-------------|----------------|--------------|--|--|
| Model(s)            | Year      | Eng. Code | Trans. Code | VIN Range From | VIN Range To |  |  |
| Atlas               | 2018-2019 | All       | All         | CA_JC000001    | CA_KC512994  |  |  |

| Revision Table  |                |                |  |  |  |  |
|-----------------|----------------|----------------|--|--|--|--|
| Instance Number | Published Date | Version Number | Reason For Update                            |  |  |  |
| 2049850/2       | 3/27/20        | 68-17-02TT     | To include model year 2019 with a VIN range. |  |  |  |
| 2049850/1       | 12/15/17       | 68-17-02TT     | Original publication.                        |  |  |  |

# **Technical Background**

Sun visor(s) are not in the correct position for normal vanity light operation.

### **Service**

A common failure is the sun visor is not seated all the way towards the extension rod mounting base as shown in figure 1.



Figure 1. **Incorrect** – Sun visor extended away from the mounting base, vanity light inoperative

Under normal operation the vanity light will not illuminate in the following positions:

Partial down position from the roof liner.

Positioned all the way forward towards the windshield. Vanity mirror cover is partially open.

Sun visor extended away from the mounting base.



#### 68-17-02TT - Driver or Passenger Vanity Light Inoperative

Release date:

3/27/2020



Figure 2. **Correct** – Sun visor in the correct position for vanity light operation.

## **Additional Information**

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

The conditions explained in figure 1 commonly happen after the sun visor is positioned to block sun light coming through the door window, and then moved back to the forward position. If this is found to be the cause of the vanity light concern, inform the customer of the proper positioning and operation.