

SSM 48660 - 2020 Mustang Shelby GT500 - Hood Ajar Indicator Illuminated And Message Displayed, Proper Procedure To Close The Hood

Some 2020 Mustang Shelby GT500 vehicles may exhibit a hood ajar indicator being illuminated, and/or a hood ajar message displayed in the information display. This may be due to the hood not being fully closed. To close the hood properly, lower the hood and allow it to drop under its own weight for the last 20-30 cm (8-12 in). The hood pins should not be utilized for indication of hood ajar position, proper adjustment or alignment. Refer to the 2020 Shelby GT500 Mustang Supplement for further information.