



Technical Service Bulletin

91 MIB2/MIB2+: e-tron-specific car menu items are not available

91 20 53 2059075/1 March 31, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, A8	2020	All	TFSI e

Condition

Customer states:

- The e-tron-specific settings in the car menu of the MMI are missing.

The following settings can be affected by this:

- Charge level.
- Auxiliary heater.
- Range.
- Statistics, etc.

Technical Background

These settings are not specified to be available in MIB Standard or MIB High Scale systems (PR No. i8S or i8E).

The customer can use these functions/settings via the myAudi app.

Production Solution

Not applicable.

Service

See *Technical Background*. Claims for replaced parts will not be reimbursed.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2059075) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.