

PCM5.0 Daylight Savings Time Not in Effect

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911 Carrera	As of 2020	992	N/A	N/A
Cayenne	As of 2019	9YA	N/A	N/A
Macan	As of 2020	95B	N/A	N/A

Revision History

Revision	Release Date	Changes
0	March 27, 2020	Original document

Condition

The customer complains that daylight savings time will not take effect. Possibly, there may be complaint that the PCM did not adjust the time when the customer changed time zones.

Technical Background

There is a mismatch between the actual time (as correctly reported by the GPS) and the time displayed to the customer by the vehicle system. The vehicle system time does not reflect the one-hour adjustments for daylight savings time or possibly the time zone change.

Service Information

You can solve this condition quickly by disabling and re-enabling automatic time sync and automatic time zone.

Follow these steps:

- a) Click on the upper right hand corner of the PCM screen. (By default a clock is located here.)
- b) Click "Time Settings" on the following menu.
- c) Then uncheck the boxes for "Automatic time sync" and "Automatic time zone".
- d) Exit this screen and repeat steps (a) and (b). Then check those same boxes.

This correction should fix the issue and the incorrect time will not be displayed again.

Warranty

Please be sure to document your findings in PQIS thoroughly.

Use the following PQIS coding:

Cause location: 91120 Navigation unit

Cause symptom: 4000 Electrical error

Search Items

DST, time zone, wrong time, hour, behind, ahead

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
