

## GPOP - Issue Review System

**Part Number:** 68428688A\$

**Part Description:** BUTTON, Glass, Backlight – EBL

**Issue Description:** Hard top back flipper glass defroster grid is inoperative due to connector tab for electric backlight defrost grid broken off.

For back flipper glass defroster terminal soldered joint failure, please send an email with the following to *FCA Redacted Content*:

VIN Number

Mileage

A close up picture of both the back of the failed soldered terminal and the glass side of the failed solder joint.

You can also speak to *FCA Redacted Content* if more information is needed. Please proceed with the repair using the repair kit as called out in the instructions.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.