

GPOP - Issue Review System

Part Number: 68053666A\$, 68299497A\$

Part Description: CASE ASSEMBLY, Differential

Issue Description: For concern of shudder/chatter/vibration from the rear axle that is more prominent during turns and customer has the following:

- 1) Limited Slip Differential
- 2) No record of rear axle oil being serviced in the last 20,000 miles
- 3) No apparent damage to the axle/differential case or differential case internal gears

Service the rear axle oil with new and test drive to see if condition is still present. If still present follow standard diagnostic procedures and contact *FCA Redacted Content* for further assistance.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
