



**NUMBER:** 23-006-20

**GROUP:** 23 - Body

**DATE:** February 6, 2020

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This bulletin supersedes Service Bulletin 23-023-19, dated August 28, 2019, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include updated parts table.**

**This Service Bulletin is also being released as Rapid Response Transmittal (RRT) 19-063, dated August 28, 2019. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

***SUBJECT:***

Front Splash Shield Contacting Tire

***OVERVIEW:***

This bulletin involves replacing both the left and right front splash shields and rivets.

***MODELS:***

2020 (JT) Jeep Gladiator (Rubicon Only)

**NOTE: This bulletin applies to vehicles within the following markets/countries: North America.**

**NOTE: This bulletin applies to vehicles built on or after March 14, 2019 (MDH 0314XX) and on or before May 29, 2019 (MDH 0529XX).**

***SYMPTOM/CONDITION:***

Customers may experience one or more of the following:

- One or both of the front splash shields are rubbing on the tires while driving over 88 kph (55 MPH), or with strong cross winds.
- Rattle noise can be heard from either front wheel area while driving.

***DIAGNOSIS:***

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition, perform the repair.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	**68351462AC**	Front Right Splash Shield
1	**68351463AC**	Front Left Splash Shield
6	06506007AA	Rivets <b>(three per splash shield)</b>

**REPAIR PROCEDURE:****NOTE: Re-use splash shield push pins.**

1. Replace both the left and right front splash shields with rivets. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info>23 - Body/Exterior/Shield, Splash, Front Wheelhouse/Removal and Installation.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
23-02-09-97	Splash Shield, Front - Replace Both (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.5 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------