

**Subject: Engineering Information – Service Engine Soon Lamp Illuminated, Oil Leak Coming from Valve Rocker Arm Oil Control Valve, DTCs P0300, P3433, P3435 or P3409 Set**

*This EI has been revised to end the need for information from the field. Please discard PIE0540.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:	
		from	to	from	to			
Buick	LaCrosse	2017	<b>2019</b>	-	-	Equipped with 3.6L Engine (RPO LGX)	<b>All</b>	
Cadillac	ATS	<b>2016</b>		-	-	-		Equipped with 3.0L, 3.6L Engine (RPOs LGX, LGW)
	CT6							Equipped with 3.6L Engine (RPO LGX)
	CTS							
	XT5	2017						Equipped with 3.6L Engine (RPO LGZ)
Chevrolet	Camaro	2016		-	-	-		Equipped with 3.6L Engine (RPO LGX)
	Colorado	2017						Equipped with 3.6L Engine (RPO LGZ)
	Blazer	2019						Equipped with 3.6L Engine (RPO LGZ)
GMC	Acadia	<b>2017</b>		-	-	-		Equipped with 3.6L Engine (RPO LGX)
	Canyon							Equipped with 3.6L Engine (RPO LGZ)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released September 17, 2019 February 10, 2020 – Ended the need for further information from the field.