Subject: Engineering Information – Vibration and/or Banging Noise Heard From Under the Vehicle

This PI has been revised to end the need for information from the field. Please discard PIE0541.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2020	-	-	-	Equipped without Transfer Case - Active Single, Two
	Silverado 1500						Speed (RPOs NP0, NQH)
GMC	Sierra 1500 (New Model)						
	Sierra 1500						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 02, 2019 Revised February 17, 2020 – Ended the need for further information from the field.