

## CAMPAIGN LAUNCH STATUS

### N445 UPS 19-20MY L550/L551 TCM SOFTWARE UPDATE



#### N445 UPS TCM SW UPDATE L550 L551

AFFECTED MODELS	19-20MY L550 L551
NAS VOLUME AFFECTED	5662 USA 644 CAN
REPAIR	Affected vehicles will have new software downloaded to the Transmission Control Module.
REPAIR TIME	0.2 hrs + 0.2 DIDO
LAUNCHED	March 9th 2020
Notes	*Approx. 200 units will be updated in ports

- Updates the TCM software calibration to prevent a possible limp home condition if DTC P2545-86 or P4546-86 are detected. The issue is likely to occur in the first 1000km. 'Transmission fault detected' message may be displayed.