



Check Engine Lamp on with a Lack of Power

16MY onward Range Rover, RR Sport, Discovery equipped with TDV6 Engine

Customer Voice:

- The Check Engine Lamp is on and there is a lack of power.

Technical Description:

- P0087-21,22,84 is stored in the PCM for fuel rail/ system pressure too low.

Status:

- Visually check for obvious signs of a leak near the filter.
- If a leak is identified, please stop working on the vehicle and raise a TA with a clear & detailed description of the customer symptoms. An engineer may be interested in visiting the vehicle directly to gather additional data. It is important that the system remain undisturbed for analysis.

