



FEAD Tensioner

17MY onward Range Rover, RR Sport, RR Velar, Discovery, F TYPE, F PACE, XE, XF, XJ equipped with AJ126

Customer Voice:

- There is a noise from the engine.
- The charge warning lamp is on.

Technical Description:

- Analysis of returned parts has identified the tensioner failure is attributed to oil intrusion into the bearing.

Status:

- Inspect for evidence of an oil leak in the area of the FEAD tensioner.
- Perform diagnosis of the root cause of the oil leak and document findings with pictures. Repair the leak as necessary.
- Raise an EPQR which includes detailed information about the source of the oil leak and pictures.

