



Blower motor inoperative due to a blown / melted fuse 5E

2017- Onwards Range Rover ,
Range Rover Sport and Discovery

Customer Voice:

- No airflow from the HVAC system.

Technical Description:

- Fuse 5E in the EJB is found blown/melted.

Status:

- This is currently under investigation.
- Before any parts are replaced, please take pictures from different angles of the fuse in the EJB.
- If the fuse is found blown, replace the fuse and check the current draw of the blower motor.
- Verify the manner in which the HVAC is normally operated.
 - HVAC is operated in manual or auto mode?
 - What is the temperature setting normally used?
 - Is the vehicle driven with A/C on and the windows open?
- Submit an EPQR with the pictures, customer usage and contact details for the parts return of the fuse and blower motor.

