



Preliminary Information

PIP5637E 3.0L (RPO LM2) Engine Exchange Program has ended

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2020	All	All	3.0L (LM2)	All
GMC	Sierra 1500 (New Model)	2020	All	All	3.0L (LM2)	All

Involved Region or Country	North America
Condition	Engine Exchange
Cause	New Product Monitoring

General Motors Technical Assistance Center part restriction for the 3.0 liter LM2 engine has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

This engine can now be ordered through the regular GM CCA parts process or PQC process for required dealers.

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the correct part to order.

Version History

Version	6
Modified	<p>04/23/2019 - Created on.</p> <p>08/14/2019 - Updated to make 2020 model year and update part number for EGR valve inlet gasket.</p> <p>8/30/2019 - Updated to update the serviceable component list</p> <p>9/5/2019 - Updated Labor OP</p> <p>9/30/2019 - Updated labor op.</p> <p>03/022020 - Updated to remove the engine from the exchange program</p>



GENERAL MOTORS