



Bulletin No.: PIP5713  
Published date: 03/9/2020

# Preliminary Information

## PIP5713 P16F3 Setting After Doing A Cylinder Deactivation Test

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2020	All	All	6.2L LT2	All

Involved Region or Country	North America
Condition	P16F3 setting after performing a cylinder deactivation test with GDS
Cause	Software anomaly

### Correction:

Clear the codes when done with the test.

**Note: Do not replace the ECM for this concern.**

### Warranty Information

### Version History

Version	<b>1</b>
Modified	03/09/2020 - Created on

