

Subject

**Steering Wheel Vibration with Dunlop P265/70R17  
Dunlop Grandtrek TiresGrandtrek Tires**

Market

USA

Service Category

Suspension

Section

Tire/Wheel

Applicability

4Runner

**APPLICABLE VEHICLES**

2019-2020

4Runner

**CONDITION**

Some 2019-2020 model year 4Runner SR5 and TRD Off Road grade models with Dunlop Grandtrek AT20 P265/70R17 tires may experience vibration (flutter) in the steering wheel when driving at highway speeds 55 mph and above.

**RECOMMENDATIONS**

Seeking Go and See on vehicles that meets these criteria:

- 1) No aftermarket wheels and/or tires
- 2) Exhibits steering wheel vibration (flutter) while driving 55 mph and above
- 3) Vehicle has less than 5,000 miles on the odometer
- 4) Vehicle has OEM P265/70R17 Dunlop Grandtrek AT20 tires
- 5) No prior repair attempts on wheels and tires (wheel/tire assemblies have never been removed from the vehicle and remain as installed by assembly plant – Do not remove the wheels/tires)

If this condition is found:

- Please contact TAS before performing any work on the vehicle.
- Please hold vehicle for a minimum of 2 hours to allow decision on go and see.
- If it is a Sunday or holiday, continue with diagnosis and repair, and contact TAS at the next available opportunity.

**LINK REFERENCES**

This Tech Tip does not contain any link references