

[Next Unread Message](#)[View Message](#)

Sent on	04	08	2020	Expires on	05	04	2020
----------------	----	----	------	-------------------	----	----	------

From	Parts and Service Division
-------------	----------------------------

Subject	**Inspection Request** 2020 HRV/Fit Engine Room Wire Harnesses
----------------	--

To: All Honda Sales and Service Managers
From: Parts and Service Division
Re: **Inspection Request** 2020 HRV/Fit Engine Room Wire Harnesses

If you receive this */N* message, you may have and/or be receiving the vehicles that are affected by this request. Please check to see if you have VINs on the list

American Honda (AHM) understands certain 2020 HRV/Fit may have wire harness damage due to vandalism at the shipping yards. Suspect units were delivered to your dealership prior to our inspection. Please inspect the engine room wire harnesses of VINs from the list that may be in your inventory.

Please click on the links below for the **affected VINs** and **Inspection Procedures** for HRV and Fit respectively.

[Click here to view affected VINs.](#)

[Click here to view HRV Inspection Procedure](#)

[Click here to view Fit Inspection Procedure](#)

If your affected unit was traded to another dealership before you could inspect it, please notify AHM Technical Research & Support (trs@ahm.honda.com) immediately.

Thank you.