



Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2012-2014	2.0L TDI (CKRA)	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2059299/1	4/17/20	15-20-02TT	Original publication.

Technical Background

Oil leak from Camshaft Seal.

Service

If oil is found leaking between the exhaust manifold and timing cover (Figure 1), check for an oil leak at camshaft seal (Figure 2). Replace the seal as needed using the procedure in the repair manual.



Figure1



Figure 2



15-20-02TT Oil Leak at Cylinder Head Area

Release date: 04/17/2020

Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.