

Subject: Engineering Information – Service Engine Soon (SES) Lamp Illuminated, DTCs B2B0D and/or B2B0E Central Gateway Module Codes Unable to Communicate with HSLAN or LSLAN

This PI has been revised to end the need for information from the field. Please discard PIE0546.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2020	-	-	-	-
GMC	Sierra 1500 (New Model)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released November 19, 2019 Revised March 26, 2020 – Ended the need for further information from the field.