CAMPAIGN LAUNCH STATUS





SERVICE ACTION N442 - TRAFFIC SIGN RECOGNITION (TSR) FUNCTIONALITY 2020 MY DISCOVERY AFFECTED MODELS **BASE SE NON-NAV VOLUME AFFECTED** 32 USA 1 CAN Affected vehicles require an update to the Car Config **REPAIR** File. Non-Nav vehicles incorrectly built with TSR and Adaptive Speed Limiter 0.2 hrs + Drive in/out REPAIR TIME April 1st 2020 REPAIR LAUNCHED Non-Nav vehicles incorrectly built with TSR and Adaptive **Notes** Speed Limiter (ASL)

SERVICE ACTION N439 – SUSPENSION FAULT MESSAGE	
AFFECTED MODELS	2020 MY RR Evoque
VOLUME AFFECTED	1,553 USA 76 CAN All retailed
REPAIR	Affected vehicles require a software update Chassis Control module (CHCM) and DTC read and clear.
REPAIR TIME	0.4 hrs + Drive in/out
REPAIR LAUNCHED	April 1 st 2020
Notes	Self Test during cranking can set a false DTC and message.