

Latest Vehicle Concern Fixes

POWERTRAIN



Check Engine Lamp on with a Lack of Power	16MY onward Range Rover, RR Sport, Discovery equipped with TDV6 Engine
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• The Check Engine Lamp is on and there is a lack of power. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• P0087-21,22,84 is stored in the PCM for fuel rail/ system pressure too low. <p><u>Status:</u></p> <ul style="list-style-type: none">• Visually check for obvious signs of a leak near the filter.• If a leak is identified, please stop working on the vehicle and raise a TA with a clear & detailed description of the customer symptoms. An engineer may be interested in visiting the vehicle directly to gather additional data. It is important that the system remain undisturbed for analysis.	

