

LATEST VEHICLE CONCERN FIXES

POWERTRAIN



Hesitation on light throttle	19MY onward Range Rover and RR Sport MHEV equipped with AJ20P6
<p>Customer Voice:</p> <ul style="list-style-type: none">• There is a hesitation on acceleration with light throttle. <p>Technical Description:</p> <ul style="list-style-type: none">• DTCs may be stored for B1S1 Oxygen Sensor. <p>Status:</p> <ul style="list-style-type: none">• Should the O2 sensor be confirmed as the root cause, please create an EPQR.• Hold the original sensor for return.• Include contact information (name, email address, and phone number) of someone at the retailer who can serve as the point of contact for the shipping company to collect the original unit.	<p>The diagram illustrates the oxygen sensor assembly for the vehicle. It shows a main sensor unit with a wiring harness. Callouts identify specific components: 13A608 (two locations), 6K288, 8F472, 8Q444A, HB1, 14A705, and 8Q444B. A dashed line indicates the connection between the main sensor and the wiring harness.</p>

