

LATEST VEHICLE CONCERN FIXES

POWERTRAIN



Tip in Hesitation	2020 Discovery Sport equipped with AJ20P4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• There is a lag when accelerating while rolling.• The vehicle is sluggish. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• No DTCs are stored, PCM and TCM software are at the most current level.• No error state is identified with the vehicle. <p><u>Status:</u></p> <ul style="list-style-type: none">• This topic is in the early stages of investigation.• Please raise an EPQR and attach a current session file to the report.• Gather as much detail about what conditions the hesitation occurs under and include that detail in the EPQR.	

