

LATEST VEHICLE CONCERN FIXES

CHASSIS



Excessive Brake Caliper Assembly Lube Found At PDI

20MY Discovery Sport, RR Evoque

Customer Voice:

- A customer/ technician may notice what they perceive as a leak from the front brake calipers during PDI.

Technical Description:

- An excessive amount of assembly lubricate may have been used during the assembly of the front brake calipers and as a result the extra lubricant may stain the back of the brake pad and caliper dust boot.

Status:

- The excessive lubricant does not affect brake system performance and is not a problem.
- It is advised that if this is noticed at PDI, clean the excessive lubricant with brake parts cleaner and a rag then road test the vehicle and recheck for any leaks to ensure that staining in this area was only excessive assembly lubricant.

