

LATEST VEHICLE CONCERN FIXES

BODY



Rattle Noise From Second Row Seat Adjustment Lever	17MY Discovery
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">A customer may report a rattle type noise from the second row seat or difficulty in moving the seat forward or rearward. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">The second row seat manual forward/ rearward adjustment lever (manual seats only) may not be adjusted properly, causing either a rattle type noise or inoperative operation. <p><u>Status:</u></p> <ul style="list-style-type: none">SSM 74609 has been published to provide guidance in adjusting the manual forward/ rearward lever.	

