



Bulletin No.: PIC6415
Published date: 04/14/2020

Preliminary Information

PIC6415 Front Brake Squeak And/Or Squeal Noise Heard At Times

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2020	Vehicles built prior to January 3, 2020	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that there is a squeal and/or squeak noise heard when applying the brakes.
Cause	A squeak or squeal noise can occur during light brake pedal application at low vehicle speeds when the brakes are first applied or lightly applied. Occasionally, this noise may appear from the front, while in reverse, after a period of non-use, such as being parked overnight, or cold brakes and/or in high humidity conditions

Correction:

If the concern has been root caused as described above, no repairs are to be completed at this time. Engineering is working on a solution.

This PI will be converted into a bulletin when new information is available.

Version History

Version	1
Modified	4/14/2020 - Created



GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.