

# Newmar Corporation

PO Box 30  
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

**RSB 553**  
**May. 5, 2020**

## RECALL SERVICE BULLETIN

### AFFECTED MODELS

2019 :: Ventana LE, Ventana, Mountain Aire, London Aire, Essex,  
2020:: Kountry Star, Mountain Aire

### DESCRIPTION

Daimler Trucks North America LLC has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis (NHTSA # 20V 127). In response, Newmar is releasing NHTSA # 20V 171.

### ISSUE

On certain motorhomes, the brake caliper bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate, potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

### UNITS AFFECTED

Please refer to the attached population list for specific VIN numbers supplied by DTNA.

### REPAIR AND PROCEDURE

DTNA-authorized service facilities will inspect and repair as necessary. DTNA will provide the work instructions and any necessary parts.

### CUSTOMER ACTION

Contact Daimler Trucks North America at 1-800-547-0712 to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department at 1-800-731-8300. A brand specialist will assist you in scheduling an appointment to have this repair completed.

### DEALER ACTION

Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/> to locate an authorized DTNA service center to schedule and perform the recall near you. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

### NOTE

Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair.

**IMPORTANT:** Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 29, 2020

Re: Newmar Corporation – Motor Vehicle Recall Notification

---

Subject: Recall Campaign No. 20V 171

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

## **REASON FOR THIS RECALL**

*In response to notification from Daimler Trucks North America LLC, Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motorhomes built on Freightliner Chassis.*

On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

## **DEALER CAMPAIGN RESPONSIBILITY**

***Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

## **REPAIR PROCEDURE**

Daimler Trucks North America will provide the work instructions.

**If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

## IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # \_\_\_\_\_

Name

Address

City, State Zip code

Date: April 29, 2020

Motor Vehicle Recall Notification - Recall Campaign No. 20V 171

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

### **REASON FOR THIS RECALL**

*Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.*

On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash. Correction: Daimler Trucks North America authorized service facilities will inspect and repair as necessary.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

### **The Safety Risk**

Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash.

### **WHAT WE WILL DO**

Daimler Trucks North America will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Estimated time for inspection/repair is 1.2--1.7 hrs.

### **WHAT YOU NEED TO DO**

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

**Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.**

*If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:*

**Service Department**  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

Date: April 29, 2020

Re: Newmar Corporation – Motor Vehicle Recall Notification

---

Subject: Recall Campaign No: 2020-119

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

## **REASON FOR THIS RECALL**

In response to notification from Daimler Trucks North America LLC, Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis.

### **Issue:**

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may not be properly tightened. This could cause the caliper bolts to loosen and result in reduced brake effectiveness.

### **Safety Risk:**

Reduced brake effectiveness could cause an increase in stopping distance and create the risk of a crash.

### **Corrective Actions:**

Daimler Trucks North America (DTNA) will notify owners by mail and instruct them to take their motorhome to an authorized DTNA Service Facility to inspect and replace the brake caliper bolts as necessary.

This recall applies to certain Newmar 2020 Mountain Aire motorhomes.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

## **DEALER/SERVICE FACILITY CAMPAIGN RESPONSIBILITY**

***Dealer/Service Facility are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

## **REPAIR PROCEDURE**

Daimler Trucks North America will provide the work instructions. DTNA Service Facility will inspect and replace the brake caliper bolts as necessary.

**If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

VIN#  
make, model, model year  
Name  
Address  
City, State Zip code

Date: April 29, 2020  
Motor Vehicle Recall Notification - Recall Campaign No: 2020-119

---

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

## **REASON FOR THIS RECALL**

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

### **Issue:**

On certain motorhomes equipped with air disc brakes, the brake caliper mounting bolts may not be properly tightened. This could cause the caliper bolts to loosen and result in reduced brake effectiveness.

### **Safety Risk:**

Reduced brake effectiveness could cause an increase in stopping distance and create the risk of a crash.

### **Corrective Actions:**

Daimler Trucks North America (DTNA) will notify owners by mail and instruct them to take their motorhome to an authorized DTNA Service Facility to inspect and replace the brake caliper bolts as necessary.

**The motorhome requires immediate service. Continued use poses a potential safety hazard.**

## **WHAT WE WILL DO**

Daimler Trucks North America LLC will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Estimated time for inspection only is 1.2 hrs. or inspection with repair is 1.7 hrs.

## **WHAT YOU NEED TO DO**

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

**Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.**

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

An Authorized Chassis Service Facility is best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

# NEWMAR CORPORATION

NEWMARCORP.COM

N° VIN  
marque, modèle, année du modèle  
Nom—  
Adresse  
Ville, province et code postal

Date : 29 avril 2020

Avis de rappel de véhicule automobile : campagne de rappel n° 2020-119

---

Cher client :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

## **RAISON DE CE RAPPEL**

Newmar Corporation a déterminé que certaines autocaravanes construites sur un châssis Freightliner présentaient un défaut lié à la sécurité. Ce rappel fait suite à des informations fournies par Daimler Trucks North America LLC.

Problème :

Sur certaines autocaravanes munies de freins à disques pneumatiques, les boulons de fixation de l'étrier de frein peuvent être mal serrés. Ce défaut pourrait entraîner le desserrage des boulons d'étrier et une diminution de l'efficacité des freins.

Risque pour la sécurité :

Une réduction de l'efficacité des freins pourrait entraîner une augmentation de la distance d'arrêt et engendrer un risque d'accident.

Mesures correctives :

Daimler Trucks North America (DTNA) avisera les propriétaires par la poste et les invitera à présenter leur autocaravane à un centre de service agréé par l'entreprise DTNA pour examen et remplacement des boulons de l'étrier de frein si nécessaire.

**Les autocaravanes nécessitent une inspection immédiate. Continuer à utiliser ces véhicules sans les faire contrôler constitue un risque potentiel pour la sécurité.**

## **CE QUE NOUS FERONS**

Daimler Trucks North America LLC fournira aux propriétaires de tous les autocaravanes concernées un recours en cas de défaut potentiel, sans frais liés aux pièces ou à la main-d'œuvre. La durée estimée de l'inspection seule est de 1,2 heure ou de 1,7 heures pour réaliser l'inspection et la réparation.

## **CE QUE VOUS DEVEZ FAIRE**

Du fait que ce défaut compromet la sécurité de véhicules automobiles, il est recommandé d'appeler Daimler Trucks North America en composant le **1-800-547-0712** pour trouver un centre de réparation agréé dans votre région. Pour toute aide supplémentaire, communiquez avec le service technique de Newmar en composant le 1-800-731-8300. Un représentant vous aidera à fixer un rendez-vous afin de faire effectuer cette réparation.

**Les réglementations fédérales exigent que tout loueur de véhicule recevant cet avis de rappel en transmette une copie au locataire dans un délai de dix jours.**

Si vous avez fait effectuer la réparation avant de recevoir cette lettre, vous pourriez être admissible à un remboursement des frais associés. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation à l'adresse suivante :

Service technique  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

Les centres certifiés d'entretien de châssis sont les mieux équipés pour obtenir des pièces et effectuer la réparation afin que votre véhicule soit réparé le plus rapidement possible. TOUTEFOIS, si vous confiez votre véhicule à votre centre certifié d'entretien de châssis à la date prévue et que la réparation n'est pas effectuée à cette date ou dans un délai de cinq jours, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1-800-731-8300.

Si vous n'êtes plus le propriétaire du véhicule concerné, veuillez nous fournir le nom et l'adresse de la personne ou du concessionnaire à qui vous l'avez vendu ou échangé. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction à l'égard des produits Newmar sont importantes pour nous. Nous vous prions de nous excuser pour tous désagréments que cette situation a pu vous causer.

Cordialement,

Newmar Corporation

| Prod#     | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|-----------|-------------------|------|-------|------|-------|---------|------------|------------|
| usa units |                   |      |       |      |       |         |            |            |
| 414600    | 4UZACHFC9KCLM7223 | 2019 | VT    | DP   | 3717  | FL      | 4/15/2019  | 4/23/2019  |
| 414177    | 4UZACHFC6KCLG5559 | 2019 | VL    | DP   | 3709  | FL      | 11/15/2018 | 11/26/2018 |
| 414289    | 4UZACHFC9KCLJ1063 | 2019 | VT    | DP   | 3412  | FL      | 11/21/2018 | 11/30/2018 |
| 414020    | 4UZFCHFE8KCLG5568 | 2019 | VT    | DP   | 4326  | FL      | 10/30/2018 | 11/6/2018  |
| 801361    | 4UZFCTFG4KCLM7447 | 2019 | EX    | DP   | 4543  | FL      | 5/14/2019  | 5/21/2019  |
| 801358    | 4UZFCTFG2KCLM7446 | 2019 | EX    | DP   | 4543  | FL      | 4/1/2019   | 4/9/2019   |
| 904751    | 4UZFCTBG6KCLM2756 | 2019 | MA    | DP   | 4533  | FL      | 3/14/2019  | 3/22/2019  |
| 501685    | 4UZFCTFG1KCLV8566 | 2019 | LA    | DP   | 4543  | FL      | 5/1/2019   | 5/8/2019   |
| 501683    | 4UZFCTFG3KCLM7441 | 2019 | LA    | DP   | 4579  | FL      | 3/25/2019  | 4/1/2019   |
| 414530    | 4UZFCHFE6KCLG5567 | 2019 | VT    | DP   | 4369  | FL      | 10/26/2018 | 11/2/2018  |
| 414605    | 4UZACHFC3KCLG5566 | 2019 | VT    | DP   | 3717  | FL      | 11/20/2018 | 11/29/2018 |
| 414030    | 4UZACHFC8KCLG5207 | 2019 | VL    | DP   | 3709  | FL      | 10/23/2018 | 10/30/2018 |
| 501641    | 4UZFCTFG9KCLM7427 | 2019 | LA    | DP   | 4543  | FL      | 1/8/2019   | 1/15/2019  |
| 414477    | 4UZACHFCXKCLM7201 | 2019 | VT    | DP   | 3407  | FL      | 3/5/2019   | 3/12/2019  |
| 414663    | 4UZACHFC7KCLM7205 | 2019 | VT    | DP   | 3412  | FL      | 3/19/2019  | 3/26/2019  |
| 414596    | 4UZACHFC3KCLH6597 | 2019 | VL    | DP   | 4037  | FL      | 10/25/2018 | 11/1/2018  |
| 501687    | 4UZFCTFG5KCLM7442 | 2019 | LA    | DP   | 4551  | FL      | 4/12/2019  | 4/22/2019  |
| 414286    | 4UZACHFC1KCLG5212 | 2019 | VT    | DP   | 3717  | FL      | 10/24/2018 | 11/1/2018  |
| 904761    | 4UZFCTFM8KCKY3242 | 2019 | MA    | DP   | 4551  | FL      | 4/18/2019  | 4/26/2019  |
| 414678    | 4UZAB2FC4KCLM7128 | 2019 | VL    | DP   | 3412  | FL      | 5/3/2019   | 5/10/2019  |
| 414071    | 4UZFCHFE9KCLM7245 | 2019 | VT    | DP   | 4037  | FL      | 2/15/2019  | 2/22/2019  |
| 501603    | 4UZFCTFG2KCLM7432 | 2019 | LA    | DP   | 4543  | FL      | 1/17/2019  | 1/24/2019  |
| 414669    | 4UZACHFC1KCLM7202 | 2019 | VT    | DP   | 3412  | FL      | 3/11/2019  | 3/18/2019  |
| 414549    | 4UZACHFC8KCLM7200 | 2019 | VT    | DP   | 3407  | FL      | 2/25/2019  | 3/5/2019   |
| 414243    | 4UZACHFC3KCLM7170 | 2019 | VL    | DP   | 4037  | FL      | 3/20/2019  | 3/27/2019  |
| 501675    | 4UZFCTFG0KCLM7431 | 2019 | LA    | DP   | 4551  | FL      | 2/28/2019  | 3/7/2019   |
| 414490    | 4UZFCHFE6KCLG5570 | 2019 | VT    | DP   | 4369  | FL      | 11/2/2018  | 11/9/2018  |
| 414677    | 4UZAB2FC6KCLM7129 | 2019 | VL    | DP   | 3426  | FL      | 5/9/2019   | 5/17/2019  |
| 414148    | 4UZACHFC5KCLJ1058 | 2019 | VL    | DP   | 3709  | FL      | 1/16/2019  | 1/23/2019  |
| 414603    | 4UZACHFC1KCLG5565 | 2019 | VT    | DP   | 3709  | FL      | 11/12/2018 | 11/19/2018 |
| 501655    | 4UZFCTFG5KCLE9946 | 2019 | LA    | DP   | 4534  | FL      | 10/29/2018 | 11/5/2018  |
| 414529    | 4UZFCHFE3KCLJ1065 | 2019 | VT    | DP   | 4369  | FL      | 12/6/2018  | 12/13/2018 |
| 501665    | 4UZFCTFG4KCLM7433 | 2019 | LA    | DP   | 4579  | FL      | 2/12/2019  | 2/20/2019  |
| 414103    | 4UZACHFC3KCLE9934 | 2019 | VL    | DP   | 3717  | FL      | 10/29/2018 | 11/5/2018  |
| 801359    | 4UZFCTFG7KCLL3557 | 2019 | EX    | DP   | 4551  | FL      | 4/17/2019  | 4/25/2019  |
| 414531    | 4UZFCHFE6KCLH6603 | 2019 | VT    | DP   | 4369  | FL      | 11/16/2018 | 11/27/2018 |
| 414458    | 4UZACHFC4KCLG5558 | 2019 | VL    | DP   | 3717  | FL      | 11/1/2018  | 11/8/2018  |
| 501691    | 4UZFCTFG3KCLV8567 | 2019 | LA    | DP   | 4551  | FL      | 5/15/2019  | 5/22/2019  |
| 414242    | 4UZACHFC0KCLM7157 | 2019 | VL    | DP   | 4037  | FL      | 12/11/2018 | 12/19/2018 |
| 414631    | 4UZFCHFE9KCLM7259 | 2019 | VT    | DP   | 4369  | FL      | 1/14/2019  | 1/21/2019  |
| 904680    | 4UZFCTBG0KCLJ4368 | 2019 | MA    | DP   | 4551  | FL      | 12/12/2018 | 12/20/2018 |
| 414106    | 4UZACHFC7KCLL7290 | 2019 | VL    | DP   | 4037  | FL      | 2/7/2019   | 2/14/2019  |
| 414380    | 4UZAB2FC1KCLE9933 | 2019 | VL    | DP   | 3426  | FL      | 11/8/2018  | 11/15/2018 |
| 413982    | 4UZFCHFE1KCLJ1064 | 2019 | VT    | DP   | 4369  | FL      | 1/22/2019  | 1/29/2019  |
| 414391    | 4UZACHFC0KCLM7224 | 2019 | VT    | DP   | 3709  | FL      | 3/21/2019  | 3/29/2019  |

|        |                    |      |    |    |      |    |            |            |
|--------|--------------------|------|----|----|------|----|------------|------------|
| 414633 | 4UZACHFC1KCLM7166  | 2019 | VL | DP | 4037 | FL | 3/7/2019   | 3/14/2019  |
| 414382 | 4UZACHFC0KCLG5556  | 2019 | VL | DP | 3717 | FL | 11/2/2018  | 11/9/2018  |
| 801357 | 4UZFACTFG5KCLL3556 | 2019 | EX | DP | 4551 | FL | 2/27/2019  | 3/7/2019   |
| 414130 | 4UZFCHFE9KCLM7262  | 2019 | VT | DP | 4369 | FL | 2/5/2019   | 2/12/2019  |
| 414252 | 4UZFCHFE1KCLM7272  | 2019 | VT | DP | 4369 | FL | 4/2/2019   | 4/9/2019   |
| 414164 | 4UZACHFC5KCLH6598  | 2019 | VL | DP | 4037 | FL | 10/16/2018 | 10/23/2018 |
| 414409 | 4UZFCHFE3KCLE9939  | 2019 | VT | DP | 4326 | FL | 10/11/2018 | 10/18/2018 |
| 414467 | 4UZACHFCXKCLG5564  | 2019 | VT | DP | 3709 | FL | 11/26/2018 | 12/3/2018  |
| 414474 | 4UZACHFC7KCLG5554  | 2019 | VL | DP | 4037 | FL | 10/5/2018  | 10/12/2018 |
| 414606 | 4UZACHFC6KCLG5562  | 2019 | VT | DP | 3717 | FL | 11/5/2018  | 11/12/2018 |
| 414069 | 4UZACHFC3KCLM7203  | 2019 | VT | DP | 3412 | FL | 3/12/2019  | 3/19/2019  |
| 801355 | 4UZFACTFGXKCLJ4372 | 2019 | EX | DP | 4543 | FL | 2/20/2019  | 2/27/2019  |
| 904654 | 4UZFACTBG9KCLJ4367 | 2019 | MA | DP | 4551 | FL | 12/6/2018  | 12/13/2018 |
| 904712 | 4UZFACTBG4KCLM2755 | 2019 | MA | DP | 4543 | FL | 2/25/2019  | 3/4/2019   |
| 414151 | 4UZACHFC0KCLL3498  | 2019 | VT | DP | 3709 | FL | 1/22/2019  | 2/1/2019   |
| 414369 | 4UZACHFC2KCLG5557  | 2019 | VL | DP | 3717 | FL | 11/6/2018  | 11/13/2018 |
| 501664 | 4UZFACTFG8KCLJ4371 | 2019 | LA | DP | 4551 | FL | 11/21/2018 | 12/3/2018  |
| 904758 | 4UZFACTFM7KCLV4057 | 2019 | MA | DP | 4551 | FL | 5/7/2019   | 5/14/2019  |
| 414598 | 4UZACHFC4KCLG5561  | 2019 | VT | DP | 3412 | FL | 10/29/2018 | 11/5/2018  |
| 501684 | 4UZFACTFG8KCLM7435 | 2019 | LA | DP | 4551 | FL | 4/10/2019  | 4/18/2019  |
| 801360 | 4UZFACTFG3KCLJ1104 | 2019 | EX | DP | 4551 | FL | 4/30/2019  | 5/7/2019   |
| 414622 | 4UZFCHFEXKCLM7240  | 2019 | VT | DP | 4054 | FL | 11/28/2018 | 12/5/2018  |
| 414189 | 4UZAB2FC3KCLM7119  | 2019 | VL | DP | 3412 | FL | 2/1/2019   | 2/8/2019   |
| 414625 | 4UZFCHFE8KCLM7267  | 2019 | VT | DP | 4369 | FL | 3/8/2019   | 3/15/2019  |
| 414365 | 4UZACHFC7KCLM7169  | 2019 | VL | DP | 4037 | FL | 3/19/2019  | 3/26/2019  |
| 414612 | 4UZACHFC4KCLM7226  | 2019 | VT | DP | 3717 | FL | 3/15/2019  | 3/25/2019  |
| 501681 | 4UZFACTFG3KCLM7438 | 2019 | LA | DP | 4551 | FL | 3/11/2019  | 3/18/2019  |
| 904741 | 4UZFACTBG9KCLJ4370 | 2019 | MA | DP | 4551 | FL | 2/4/2019   | 2/11/2019  |
| 413948 | 4UZACHFC9KCLL7288  | 2019 | VL | DP | 3717 | FL | 12/10/2018 | 12/17/2018 |
| 414607 | 4UZAB2FC9KCLM7125  | 2019 | VL | DP | 3412 | FL | 2/18/2019  | 2/25/2019  |
| 414643 | 4UZACHFC5KCLM7140  | 2019 | VL | DP | 3709 | FL | 12/18/2018 | 1/9/2019   |
| 501618 | 4UZFACTFG5KCLM7439 | 2019 | LA | DP | 4543 | FL | 3/5/2019   | 3/12/2019  |
| 904674 | 4UZFACTBG2KCLM2754 | 2019 | MA | DP | 4551 | FL | 3/12/2019  | 3/19/2019  |
| 414014 | 4UZFCHFE7KCLG8266  | 2019 | VT | DP | 4002 | FL | 12/10/2018 | 12/17/2018 |
| 414264 | 4UZFCHFEXKCLE9940  | 2019 | VT | DP | 4369 | FL | 10/3/2018  | 10/10/2018 |
| 414395 | 4UZACHFC8KCLG5563  | 2019 | VT | DP | 3709 | FL | 12/14/2018 | 1/7/2019   |
| 414169 | 4UZACHFC9KCLG5555  | 2019 | VL | DP | 4002 | FL | 11/13/2018 | 11/20/2018 |
| 904735 | 4UZFACTBG0KCLH6610 | 2019 | MA | DP | 4543 | FL | 11/5/2018  | 11/12/2018 |
| 414174 | 4UZAB2FC3KCLJ1057  | 2019 | VL | DP | 3426 | FL | 11/14/2018 | 11/21/2018 |
| 414058 | 4UZFCHFEXKCLG5569  | 2019 | VT | DP | 4310 | FL | 12/12/2018 | 12/19/2018 |
| 501644 | 4UZFACTFG9KCLM7444 | 2019 | LA | DP | 4551 | FL | 5/9/2019   | 5/16/2019  |
| 414347 | 4UZAB2FC0KCLM2685  | 2019 | VL | DP | 3412 | FL | 2/28/2019  | 3/7/2019   |
| 904739 | 4UZFACTBG6KCLL3555 | 2019 | MA | DP | 4551 | FL | 12/3/2018  | 12/10/2018 |
| 501660 | 4UZFACTFGXKCLH6611 | 2019 | LA | DP | 4533 | FL | 11/16/2018 | 11/27/2018 |
| 414028 | 4UZACHFC1KCLG5209  | 2019 | VT | DP | 3709 | FL | 10/16/2018 | 10/23/2018 |
| 414610 | 4UZACHFC4KCLG8265  | 2019 | VT | DP | 3412 | FL | 11/19/2018 | 11/29/2018 |
| 801323 | 4UZFACTFG0KCLM7445 | 2019 | EX | DP | 4551 | FL | 3/25/2019  | 4/1/2019   |

|        |                   |      |    |    |      |    |            |            |
|--------|-------------------|------|----|----|------|----|------------|------------|
| 501670 | 4UZFG0KCLJ1075    | 2019 | LA | DP | 4533 | FL | 11/19/2018 | 11/28/2018 |
| 501594 | 4UZFG7KCLM7443    | 2019 | LA | DP | 4551 | FL | 4/25/2019  | 5/3/2019   |
| 414621 | 4UZACHFC9KCLL3497 | 2019 | VT | DP | 3709 | FL | 12/20/2018 | 1/11/2019  |
| 501642 | 4UZFG1KCLM7437    | 2019 | LA | DP | 4551 | FL | 3/21/2019  | 3/29/2019  |
| 414042 | 4UZACHFC7KCLH6599 | 2019 | VT | DP | 3412 | FL | 11/27/2018 | 12/4/2018  |
| 414613 | 4UZACHFC2KCLM2686 | 2019 | VL | DP | 3717 | FL | 12/7/2018  | 12/17/2018 |
| 501662 | 4UZFG2KCLL7306    | 2019 | LA | DP | 4551 | FL | 12/17/2018 | 1/8/2019   |
| 501676 | 4UZFGXKCLM7436    | 2019 | LA | DP | 4551 | FL | 3/1/2019   | 3/8/2019   |
| 414639 | 4UZACHFC9KCLL7291 | 2019 | VL | DP | 4037 | FL | 2/7/2019   | 2/14/2019  |
| 414171 | 4UZACHFC6KCLM2688 | 2019 | VL | DP | 4037 | FL | 12/7/2018  | 12/14/2018 |
| 414290 | 4UZACHFC5KCLE9935 | 2019 | VT | DP | 3407 | FL | 10/25/2018 | 11/1/2018  |
| 413975 | 4UZACHFC7KCLJ1062 | 2019 | VT | DP | 3407 | FL | 12/4/2018  | 12/11/2018 |
| 501592 | 4UZFG9KCLM7430    | 2019 | LA | DP | 4576 | FL | 1/15/2019  | 1/21/2019  |
| 904743 | 4UZFBG2KCLJ4369   | 2019 | MA | DP | 4551 | FL | 12/20/2018 | 1/11/2019  |
| 414250 | 4UZCFE7KCLM7244   | 2019 | VT | DP | 4037 | FL | 2/21/2019  | 2/28/2019  |
| 501646 | 4UZFG1KCLM7440    | 2019 | LA | DP | 4551 | FL | 4/5/2019   | 4/12/2019  |
| 414237 | 4UZACHFC2KCLM7225 | 2019 | VT | DP | 3717 | FL | 3/20/2019  | 3/27/2019  |
| 501671 | 4UZFG0KCLM7428    | 2019 | LA | DP | 4550 | FL | 1/9/2019   | 1/15/2019  |
| 414660 | 4UZACHFC6KCLM7227 | 2019 | VT | DP | 3709 | FL | 4/3/2019   | 4/11/2019  |
| 414123 | 4UZACHFCXKCLM7215 | 2019 | VT | DP | 3717 | FL | 2/5/2019   | 2/12/2019  |
| 750103 | 4UZACHFC2LCLL6159 | 2020 | KS | DP | 3709 | FL | 2/14/2019  | 2/22/2019  |
| 414102 | 4UZACHFC4KCLM7145 | 2019 | VL | DP | 3709 | FL | 4/3/2019   | 4/10/2019  |
| 414045 | 4UZACHFC5KCLJ1061 | 2019 | VL | DP | 4045 | FL | 11/9/2018  | 11/16/2018 |
| 414047 | 4UZACHFC7KCLJ1059 | 2019 | VL | DP | 3709 | FL | 3/12/2019  | 3/19/2019  |
| 414083 | 4UZACHFC2KCLG5560 | 2019 | VL | DP | 3709 | FL | 11/16/2018 | 11/27/2018 |
| 801327 | 4UZFG1KCLH6612    | 2019 | EX | DP | 4551 | FL | 11/21/2018 | 11/30/2018 |
| 501612 | 4UZFG2KCLM7429    | 2019 | LA | DP | 4579 | FL | 1/16/2019  | 1/23/2019  |
| 414470 | 4UZAB2FC5KCLG5553 | 2019 | VL | DP | 3426 | FL | 11/8/2018  | 11/15/2018 |
| 414423 | 4UZACHFC5KCLM7204 | 2019 | VT | DP | 3407 | FL | 3/14/2019  | 3/21/2019  |
| 501682 | 4UZFG4LCLL6157    | 2020 | LA | DP | 4559 | FL | 2/19/2019  | 2/26/2019  |
| 414190 | 4UZAB2FC0KCLM7126 | 2019 | VL | DP | 3412 | FL | 4/5/2019   | 4/12/2019  |
| 414185 | 4UZAB2FC4KCLJ9507 | 2019 | VL | DP | 3412 | FL | 2/14/2019  | 2/21/2019  |
| 904760 | 4UZFBG8KCLM2757   | 2019 | MA | DP | 4543 | FL | 4/4/2019   | 4/11/2019  |
| 801353 | 4UZFG3LCLL5968    | 2020 | EX | DP | 4533 | FL | 12/12/2018 | 12/19/2018 |
| 501679 | 4UZFG6KCLM7434    | 2019 | LA | DP | 4551 | FL | 2/15/2019  | 2/22/2019  |
| 414497 | 4UZACHFC4KCLM7193 | 2019 | VT | DP | 3426 | FL | 1/25/2019  | 2/5/2019   |
| 414515 | 4UZACHFC2KCLM7144 | 2019 | VL | DP | 3717 | FL | 3/13/2019  | 3/20/2019  |

Canadian units

|        |                  |      |    |    |      |    |           |           |
|--------|------------------|------|----|----|------|----|-----------|-----------|
| 904747 | 4UZFTFM5LCLL6156 | 2020 | MA | DP | 4551 | FL | 1/11/2019 | 1/24/2019 |
|--------|------------------|------|----|----|------|----|-----------|-----------|