

GPOP - Issue Review System

Part Number: 68319146A\$

Part Description: TUBE, Coolant outlet (Rear Heater Return Line)

Issue If looking to replace the rear heater line due to a rub through from the trans oil
Description: heater (TOH) line clamp on the engine side:

- 1) Rotate the tangs on the clamp towards the transmission and out of the direction of the rear heater line
- 2) Adjust the TOH line by pushing it towards the engine to increase clearance between the TOH line and rear heater line.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
