



# Technical Journal

TITLE:

**Ping noise from exhaust when cooling down**

<b>REF NO:</b> TJ 34787.2.1	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2020-04-08	<b>STATUS DATE:</b> 2020-04-24
<b>FUNC GROUP:</b> 2520	<b>FUNC DESC:</b> Silencer and exhaust pipe	Page 1 of 2	

“Right first time in Time”

## Attachment

File Name	File Size
<a href="#">Abnormal ping sound.m4a</a>	1.3555 MB

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2020		-	201846-202011
224							2019-2020		-	201835-202011
225							2019-2020		-	201817-202011
227							2019-2020		-	201846-202011
234							2017-2018		-	201617-209952
235							2017-2020		-	201624-202011
236							2017-2020		-	201646-202011
246							2018-2020		-	201717-202011
256							2016-2020		-	201505-202011

## CSC Customer Symptom Codes

Code	Description
XB	Exhaust system/Rattle/rumble

## VST Operation Number



## **DTC** Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## **Text**

### **DESCRIPTION:**

If an abnormal ping sound from the silencer occurs when cooling down. (Listen in attachment after 8 seconds and 35 seconds)

Follow action under “service”

### **SERVICE:**

Certain model year/vehicle types have an updated muffler in production that may quiet the noise to an acceptable level. The latest supersession should be used in VIDA. A VOR (Vehicle Off Road) may be required to receive the improved version part. A customer vehicle should be released until parts are available at dealer to be installed.

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report . Use concern area “Vehicle Report” and sub concern area “Support needed”, use function group 2520 if this does not remedy the concern.

**This TJ has one sound file.**